

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS
FLA,
17-PENSA,
62-

U.S. Naval Air Station,
Aircraft Repair Shop (Building 104)
Pensacola
Escambia County
Florida

HABS No. FL-250

Documentation: 3 exterior photos (1974)
2 interior photos (1974)

Jack Boucher, Photographer March 1974

FL-250-1 GENERAL VIEW, FROM NORTHWEST

FL-250-2 WEST FRONT

FL-250-3 SOUTH SIDE, FROM SOUTHEAST

FL-250-4 VIEW OF REPAIR SHOP

FL-250-5 DETAIL OF TRUSS SYSTEM

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

ADDENDUM TO:
U.S. NAVAL AIR STATION, AIRCRAFT REPAIR SHOP
(Building No. 104)
Pensacola
Escambia County
Florida

HABS FL-250

Photographs FL-250-1 through FL-250-5 were previously transmitted to the Library of Congress.

INDEX TO BLACK AND WHITE PHOTOGRAPHS

Alan Karchmer, photographer, July 1989

FL-250-6	SOUTH ELEVATION
FL-250-7	EAST ELEVATION, PARTIAL VIEW FROM SECOND FLOOR OF ADJACENT STRUCTURE
FL-250-8	EAST ELEVATION, PARTIAL VIEW
FL-250-9	WEST ELEVATION
FL-250-10	SOUTH AND PARTIAL EAST ELEVATION
FL-250-11	WEST AND SOUTH ELEVATION
FL-250-12	INTERIOR FROM WEST WALL LOOKING EAST SHOWING BUTTERFLY TRUSS CONSTRUCTION
FL-250-13	INTERIOR VIEW OF WEST WALL, NORTH END
FL-250-14	INTERIOR DETAIL OF NORTHWEST CORNER
FL-250-15	INTERIOR VIEW OF SOUTH WALL, WEST END, SHOWING DOOR CONSTRUCTION DETAIL
FL-250-16	INTERIOR OF SOUTH WALL LOOKING WEST, TAKEN FROM MEZZANINE

U.S. NAVAL AIR STATION, AIRCRAFT REPAIR SHOP

HABS FL-250

INDEX TO PHOTOGRAPHS

FL-250-17	INTERIOR DETAIL OF SOUTH WALL FROM MEZZANINE SHOWING COLUMN/TRUSS CONNECTION WITH KNEE BRACE
FL-250-18	INTERIOR DETAIL OF COLUMN BASE, SOUTH WALL
FL-250-19	INTERIOR DETAIL OF BUTTERFLY TRUSS, PARTIAL VIEW FROM MEZZANINE
FL-250-20	INTERIOR DETAIL OF BUTTERFLY TRUSS, PARTIAL VIEW FROM MEZZANINE
FL-250-21	INTERIOR OF NORTH WALL, LOOKING WEST, TAKEN FROM MEZZANINE